

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 2 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same**Amendments to the Claims**

This listing of claims replaces all prior versions, and listings, of claims in the above-identified application:

List of Claims

1. (Currently Amended) A graphical user interface for providing real-time process information to a user with regard to a process that is operable under control of one or more process variables, the graphical user interface comprising:

a scale extending along a gauge axis;

one or more bars extending along the gauge axis with the scale, each bar representative of a set of high and low process limit values for a process variable, wherein the one or more bars extending along the gauge axis comprises:

a first bar extending along the gauge axis, wherein a first end of the first bar is representative of an user set engineering hard high limit for the process variable and a second end of the first bar is representative of an user set engineering hard low limit for the process variable, wherein the first end and second end of the first bar representative of the engineering hard high and hard low limits define a range in which operator set high and low limits are set; and

a second bar extending along the gauge axis, wherein a first end of the second bar is representative of the operator set high limit for the process variable and a second end of the second bar is representative of the operator set low limit for the process variable, wherein the first end and second end of the second bar representative of the operator set high and low limits define a range in which the process is free to operate, wherein each of the operator set high and low limits are adjustable so as to exert influence on the process; and

a graphical shape displayed along the gauge axis representative of a current value of the process variable.

BEST AVAILABLE COPY

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 3 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

2. Canceled

3. Canceled

4. Canceled

5. Canceled

6. (previously presented) The graphical user interface of claim 1, wherein the second bar extending along the gauge axis representative of operator set high and low limits for the process variable extends along the gauge axis within the first bar representative of the engineering hard high and low limits for the process variable.

7. (previously presented) The graphical user interface of claim 6, wherein the one or more bars extending along the gauge axis further comprise a delta soft high region within the second bar and adjacent the first end thereof and a delta soft low region within the second bar and adjacent the second end thereof, and further wherein the delta soft high region and the delta soft low region are representative of a delta optimization range within the operator set high and low limits.

8. (original) The graphical user interface of claim 7, wherein the delta soft high region and the delta soft low region overlap within the second bar to provide for optimization to a pseudo set point.

9. (previously presented) The graphical user interface of claim 1, wherein the graphical user interface further comprises user manipulation elements movable to change one or more of the high and low process limit values.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 4 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

10. (original) The graphical user interface of claim 9, wherein the scale extending along the gauge axis is automatically adjustable as a function of the movement of the user manipulation elements.

11. (previously presented) The graphical user interface of claim 9, wherein the user manipulation elements comprise one or more manipulation pointer flags associated with operator set limits, the one or more manipulation pointer flags are draggable along the gauge axis to change such operator set limits.

12. (previously presented) The graphical user interface of claim 9, wherein the user manipulation elements comprise one or more manipulation pointer flags associated with the engineering hard limits, the one or more manipulation pointer flags are draggable along the gauge axis to change such engineering hard limits.

13. (original) The graphical user interface of claim 1, wherein the graphical shape representative of the current value of the process variable is a pointing device proximate to the scale.

14. (previously presented) The graphical user interface of claim 1, wherein the graphical user interface further comprises at least one additional graphical shape displayed along the gauge axis representative of at least one additional value for the process variable.

15. (original) The graphical user interface of claim 14, wherein the additional graphical shape representative of at least one additional value for the process variable has a color of a set of colors that reflects the state of the current value for the process variable relative to the set of high and low process limit values.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 5 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

16. (original) The graphical user interface of claim 1, wherein the scale extending along the gauge axis is adjustable as a function of a current value of the process variable relative to the one or more process limits values.

17. (original) The graphical user interface of claim 1, wherein the graphical shape representative of the current value of the process variable has a color of a set of colors that reflects the state of the current value for the process variable relative to the set of high and low process limit values.

18. (original) The graphical user interface of claim 17, wherein a color for the graphical shape represents one of a current value of the corresponding process variable being within the set of high and low process limit values, the current value of the corresponding process variable being within a certain percentage of a limit value of the set of high and low process limit values, and the current value of the corresponding process variable being outside of the set of high and low process limit values.

19. (original) The graphical user interface of claim 1, wherein a background of a region adjacent the one or more bars along the gauge axis is of a color when the graphical shape representative of the current value of the process variable is outside of the high and low process limit values, and further wherein the region is representative of engineering physical limits of the process variable.

20. (previously presented) The graphical user interface of claim 1, wherein the graphical user interface further comprises a trend graph for the process variable.

21. (previously presented) The graphical user interface of claim 20, wherein the trend graph comprises at least one of a historical trend graph and a prediction trend graph for displaying trend information representative of process variable values.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure Page 6 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

22. (previously presented) The graphical user interface of claim 20, wherein the trend graph comprises at least one of a historical trend graph and a prediction trend graph for displaying trend information representative of process variable limits.

23. (previously presented) The graphical user interface of claim 1, wherein the one or more process variables comprise a plurality of manipulated variables and a plurality of controlled variables of a continuous multivariable process.

24. (Currently Amended) A computer implemented method for providing a graphical user interface for providing real-time process information to a user for a process that is operable under control of one or more process variables, the method comprising:

displaying a scale extending along a gauge axis;

displaying one or more bars extending along the gauge axis with the scale, each bar representative of a set of high and low process limit values for a process variable, wherein displaying one or more bars extending along the gauge axis comprises:

displaying a first bar extending along the gauge axis, wherein a first end of the first bar is representative of an user set engineering hard high limit for the process variable and a second end of the first bar is representative of an user set engineering hard low limit for the process variable; and

displaying a second bar extending along the gauge axis, wherein a first end of the second bar is representative of an operator set high limit for the process variable and a second end of the second bar is representative of an operator set low limit for the process variable;

providing data representative of at least the current value of the process variable; and

displaying a graphical shape along the gauge axis representative of the current value of the process variable relative to the set of high and low process limit values; and

adjusting at least one of the high and low limits so as to exert influence on the process.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure Page 7 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

25. Canceled

26. Canceled

27. (previously presented) The method of claim 24, wherein displaying one or more bars extending along the gauge axis further comprises displaying a delta soft high region within the second bar and adjacent the first end thereof and a delta soft low region within the second bar and adjacent the second end thereof, and further wherein the delta soft high region and the delta soft low region are representative of a delta optimization range within the operator set high and low limits.

28. Canceled

29. (previously presented) The method of claim 24, wherein displaying the one or more bars extending along the gauge axis comprises displaying the second bar extending along the gauge axis representative of the operator set high and low limits for the process variable within the first bar representative of engineering hard high and low limits for the process variable.

30. (previously presented) The method of claim 29, wherein displaying one or more bars extending along the gauge axis further comprises displaying a delta soft high region within the second bar and adjacent the first end thereof and a delta soft low region within the second bar and adjacent the second end thereof, and further wherein the delta soft high region and the delta soft low region are representative of a delta optimization range within the operator set high and low limits.

31. (previously presented) The method of claim 29, wherein displaying the delta soft high region within the second bar and adjacent the first end thereof and a delta soft low region within the second bar and adjacent the second end thereof comprises:

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 8 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

receiving user input representative of the delta values; and
displaying a delta soft high region and a delta soft low region that overlap providing for
an optimization pseudo set point within the operator set high and low limits.

32. (original) The method of claim 31, wherein the optimization pseudo set point is
proportional to the delta soft high region and delta soft low region.

33. (previously presented) The method of claim 24, wherein the method further comprises:
displaying user manipulation elements movable to change one or more of the high and
low process limit values;
moving such user manipulation elements to generate data representative of changed high
or low process limit values; and
providing such data to a controller of the process.

34. (previously presented) The method of claim 33, wherin the method further comprises
rescaling the scale extending along the gauge axis as a function of the movement of the user
manipulation elements.

35. (previously presented) The method of claim 33, wherein moving such user manipulation
elements to generate data comprises dragging one or more manipulation pointer flags associated
with the operator set limits along the gauge axis to change such operator set limits.

36. (previously presented) The method of claim 33, wherein moving such user manipulation
elements to generate data comprises dragging one or more manipulation pointer flags associated
with the engineering hard limits along the gauge axis to change such engineering hard limits.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 9 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

37. (previously presented) The method of claim 33, wherein moving such user manipulation elements to generate data comprises dragging one or more manipulation pointer flags associated with the delta soft limits along the gauge axis to change such delta soft limits.

38. (original) The method of claim 24, wherein the graphical shape representative of the current value of the process variable is a pointing device proximate to the scale extending along the gauge axis.

39. (previously presented) The method of claim 24, wherein the method further comprises displaying at least one additional graphical shape along the gauge axis representative of an additional value for the process variable.

40. (previously presented) The method of claim 39, wherein displaying the at least one additional graphical shape comprises displaying at least one additional pointing device proximate to the scale extending along the gauge axis.

41. (previously presented) The method of claim 24, wherein the method further comprises rescaling the scale extending along the gauge axis as a function of the current value of the process variable relative to the set of high and low process limit values.

42. (previously presented) The method of claim 24, wherein displaying the graphical shape representative of the current value of the process variable comprises:

determining a state of the current value of the process value relative to the set of high and low process limit values; and

displaying the graphical shape in a color of a set of colors that reflects the state of the current value for the process variable.

43. (previously presented) The method of claim 42, wherein determining the state of the

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 10 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

current value of the process value relative to the set of high and low process limit values comprises determining whether the current value of the process variable is within the set of high and low process limit values, determining whether the current value of the process variable is within a certain percentage of a limit value of the set of high and low process limit values, and determining whether the current value of the process variable is a certain percentage outside of the set of high and low process limit values.

44. (previously presented) The method of claim 24, wherein the method further comprises: determining whether the current value of the process variable is outside of the set of high and low process limit values; and

displaying a graphical element representative of engineering physical limits of the process variable when the current value of the process variable is outside the set of high and low process limit values.

45. (previously presented) The method of claim 44, wherein displaying a graphical element representative of engineering physical limits of the process variable comprises displaying a background region adjacent the one or more bars along the gauge axis in a particular color representative of engineering physical limits.

46. (previously presented) The method of claim 24, wherein the method further comprises displaying a trend graph for the process variable with the displayed scale, one or more bars, and the graphical shape representative of the current value of the process variable.

47. (previously presented) The method of claim 46, wherein displaying the trend graph comprises displaying at least one of a historical trend graph and a prediction trend graph for the process variable representative of process variable values.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure Page 11 of 24**Serial No.:** 09/346,412**Confirmation No.:** 2387**Filed:** July 1, 1999**For:** Process Variable Gauge Interface and Methods Regarding Same

48. (previously presented) The method of claim 46, wherein displaying the trend graph comprises displaying at least one of a historical trend graph and a prediction trend graph for the process variable representative of process variable limits.

49. (previously presented) A graphical user interface for providing real-time process information to a user with regard to a process that is operable under control of one or more process variables, the graphical user interface comprising:

a scale extending along a gauge axis;

one or more bars extending along the gauge axis, each bar representative of a set of high and low process limit values for a process variable, wherein the one or more bars extending along the gauge axis comprise a first bar extending along the gauge axis, wherein a first end of the first bar is representative of an operator set high limit for the process variable and a second end of the first bar is representative of an operator set low limit for the process variable, and further wherein the one or more bars extending along the gauge axis further comprise a delta soft high region within the first bar and adjacent the first end thereof and a delta soft low region within the first bar and adjacent the second end thereof, and further wherein the delta soft high region and the delta soft low region are representative of a delta optimization range within the operator set high and low limits; and

a graphical shape displayed along the gauge axis representative of a current value of the process variable.

50. (previously presented) The graphical user interface of claim 49, wherein the one or more bars extending along the gauge axis further comprise a second bar extending along the gauge axis, wherein a first end of the second bar is representative of an engineering hard high limit for the process variable and a second end of the second bar is representative of an engineering hard low limit for the process variable.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure Page 12 of 24**Serial No.:** 09/346,412**Confirmation No.:** 2387**Filed:** July 1, 1999**For:** Process Variable Gauge Interface and Methods Regarding Same

51. (previously presented) The graphical user interface of claim 50, wherein the first bar extending along the gauge axis representative of operator set high and low limits for the process variable extends along the gauge axis within the second bar representative of the engineering hard high and low limits for the process variable.

52. (previously presented) The graphical user interface of claim 49, wherein the delta soft high region and the delta soft low region overlap within the first bar to provide for optimization to a pseudo set point.

53. (previously presented) A computer implemented method for providing a graphical user interface for providing real-time process information to a user for a process that is operable under control of one or more process variables, the method comprising:

displaying a scale extending along a gauge axis;

displaying one or more bars extending along the gauge axis, each bar representative of a set of high and low process limit values for a process variable, wherein displaying one or more bars extending along the gauge axis comprises displaying a first bar extending along the gauge axis, wherein a first end of the first bar is representative of an operator set high limit for the process variable and a second end of the first bar is representative of an operator set low limit for the process variable, and wherein displaying one or more bars extending along the gauge axis further comprises displaying a delta soft high region within the first bar and adjacent the first end thereof and a delta soft low region within the first bar and adjacent the second end thereof, and further wherein the delta soft high region and the delta soft low region are representative of a delta optimization range within the operator set high and low limits;

providing data representative of at least the current value of the process variable; and

displaying a graphical shape along the gauge axis representative of the current value of the process variable relative to the set of high and low process limit values.

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 13 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

54. (previously presented) The method of claim 53, wherein displaying one or more bars extending along the gauge axis comprises displaying a second bar extending along the gauge axis, wherein a first end of the second bar is representative of an engineering hard high limit for the process variable and a second end of the second bar is representative of an engineering hard low limit for the process variable.

55. (previously presented) The method of claim 53, wherein displaying the one or more bars extending along the gauge axis comprises displaying the first bar extending along the gauge axis representative of the operator set high and low limits for the process variable within the second bar representative of engineering hard high and low limits for the process variable.

56. (previously presented) The method of claim 53, wherein displaying the delta soft high region within the first bar and adjacent the first end thereof and a delta soft low region within the first bar and adjacent the second end thereof comprises:

receiving user input representative of the delta values; and

displaying a delta soft high region and a delta soft low region that overlap providing for an optimization pseudo set point within the operator set high and low limits.

57. (previously presented) The method of claim 56, wherein the optimization pseudo set point is proportional to the delta soft high region and delta soft low region.

58. (Currently Amended) A graphical user interface for providing real-time process information to a user with regard to a process that is operable under control of one or more process variables, the graphical user interface comprising:

a scale extending along a gauge axis;

one or more bars extending along the gauge axis with the scale, each bar representative of a set of high and low process limit values for a process variable, wherein the one or more bars extending along the gauge axis comprise:

Amendment and Response Under 37 C.F.R. §1.116 - Expedited Examining Procedure

Page 14 of 24

Serial No.: 09/346,412

Confirmation No.: 2387

Filed: July 1, 1999

For: Process Variable Gauge Interface and Methods Regarding Same

a first bar extending along the gauge axis, wherein a first end of the first bar is representative of an user set engineering hard high limit for the process variable and a second end of the first bar is representative of an user set engineering hard low limit for the process variable; wherein the first end and second end of the first bar representative of the engineering hard high and hard low limits define a range in which operator set high and low limits are set; and

a second bar extending along the gauge axis, wherein a first end of the second bar is representative of the operator set high limit for the process variable and a second end of the second bar is representative of an operator set low limit for the process variable, wherein the first end and second end of the second bar representative of the operator set high and low limits define a range in which the process is free to operate, wherein each of the operator set high and low limits are adjustable so as to exert influence on the process, and further wherein the second bar extends along the gauge axis within the first bar representative of the engineering hard high and low limits for the process variable; a graphical shape displayed along the gauge axis representative of a current value of the process variable; and

user manipulation elements movable to change one or more of the high and low process limit values.

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.